

WELL NAME: LORENCITO 10-2, API #: 071-07123, INSP. # 695109419



PHOTO 1: WELL SIGN





PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 4: AREA OF IMPACTED SOIL NEAR DRIVEHEAD (HYDRAULIC OIL IS LEAKING FROM DRIVE MOTOR). Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 4-18-2024.





PHOTO 5: DRIVEHEAD IS LEAKING HYDRAULIC OIL (IT IS HARD TO SEE IN PHOTO HOWEVER THERE IS AN ACTIVE DRIP OF HYDRAULIC OIL DRIPPING OFF OF DRIVEHEAD NEAR HOSES ON GEAR BOX. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. DUE TO ACTIVE LEAK REPAIR MUST BE DONE WITHIN 24 HOURS CA DATE 4-12-2024. LEFT A VOICMAIL FOR LAWRENCE BOWMAN REGARDING LEAKS.

