



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 242322 Type: WELL API Number: 123-10113 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/24/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>Follow up inspection to Doc# 713300016 in response to FIRR #403593663. Based on photos submitted by operator all corrective actions appear to have not been completed.                      Mechanical issues: rule 608E corrective action date 9-17-23                      Unused equipment: Rule 606 corrective action date 9-17-23                      MIT; Rule 417B corritive action date 9-17-23</p> <p>COMPLETED corrective action                      Weeds; Rule 606 corrective action date 9-17-23                      corrective actions appear to have been completed.</p>	kesterm	04/09/2024