

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2024

Submitted Date:

04/12/2024

Document Number:

708903530

FIELD INSPECTION FORM

Loc ID 383326 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

44 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301722	WELL	PR	07/15/2013	GW	045-18240	YOUBERG RWF 33-23	PR
301723	WELL	PR	08/01/2014	GW	045-18241	YOUBERG RWF 333-23	PR
301724	WELL	PR	08/01/2014	GW	045-18242	YOUBERG RWF 433-23	PR
301725	WELL	PR	10/10/2013	GW	045-18243	YOUBERG RWF 534-23	PR
301726	WELL	PR	10/10/2013	GW	045-18244	YOUBERG RWF 343-23	PR
301727	WELL	PR	07/15/2013	GW	045-18245	YOUBERG RWF 43-23	PR
301728	WELL	PR	07/15/2013	GW	045-18246	YOUBERG RWF 533-23	PR
301729	WELL	PR	08/07/2013	GW	045-18247	YOUBERG RWF 34-23	PR
301730	WELL	PR	10/10/2013	GW	045-18248	YOUBERG RWF 544-23	PR
301731	WELL	PR	07/31/2013	GW	045-18249	YOUBERG RWF 444-23	PR
301732	WELL	PR	08/07/2013	GW	045-18250	YOUBERG RWF 344-23	PR
301733	WELL	PR	08/01/2014	GW	045-18251	YOUBERG RWF 443-23	PR
301734	WELL	PR	10/10/2013	GW	045-18252	YOUBERG RWF 44-23	PR
301735	WELL	PR	10/10/2013	GW	045-18253	YOUBERG RWF 334-23	PR
301736	WELL	PR	08/01/2014	GW	045-18254	YOUBERG RWF 434-23	PR

General Comment:

CECMC Inspection Report Summary

On 04/03/2024 at approximately 11:51 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC YOUBERG RWF 33-23 Pad.
Location # 383326 in Garfield County Colorado.

Please refer to inspection 708901765 conducted on 09/22/2023, 1 of 2 previous corrective actions has been completed. Equipment/PRV
CA has been completed. Unable to determine if Housekeeping/Stained soils & gravel CA has been completed due to recent precipitation,
the area around wellheads had not dried out at time of inspection.

Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area.
Location is approximately 183 yards from Beaver Creek & approximately 322 yards from the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris/dead weeds - please refer to photo log		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sand traps - hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Liquid nitrogen tank, air compressor & thermoelectric generator - hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - Cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermoelectric generator		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Sand traps		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 15		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Air compressor		
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: <u>301722</u>	Type: <u>WELL</u>	API Number: <u>045-18240</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing, well on plunger lift</u>	Corrective Action:		Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>301723</u>	Type: <u>WELL</u>	API Number: <u>045-18241</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing, well on plunger lift</u>	Corrective Action:		Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>301724</u>	Type: <u>WELL</u>	API Number: <u>045-18242</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing, well on plunger lift</u>	Corrective Action:		Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>301725</u>	Type: <u>WELL</u>	API Number: <u>045-18243</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing, well on plunger lift</u>	Corrective Action:		Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>301726</u>	Type: <u>WELL</u>	API Number: <u>045-18244</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment: <u>Shut In</u>	Corrective Action:		Date: _____
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>301727</u>	Type: <u>WELL</u>	API Number: <u>045-18245</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing, well on plunger lift</u>	Corrective Action:		Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: <u>301728</u>	Type: <u>WELL</u>	API Number: <u>045-18246</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>Producing, well on plunger lift</u>	Corrective Action:		Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			

Facility ID: 301729 Type: WELL API Number: 045-18247 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 301730 Type: WELL API Number: 045-18248 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 301731 Type: WELL API Number: 045-18249 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 301732 Type: WELL API Number: 045-18250 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 301733 Type: WELL API Number: 045-18251 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 301734 Type: WELL API Number: 045-18252 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 301735 Type: WELL API Number: 045-18253 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 301736 Type: WELL API Number: 045-18254 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
		Gravel				Sparse
Compaction						Some areas of light compaction
				Material Handling And Spill Prevention		Chemical tank containments
Gravel						Sparse to none in areas
Ditches						
		Compaction				

Comment: [Some fluid in chemical tank containments, may need maintenance in the near future.](#)

[Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Any corrective actions from previous inspections that have not been addressed are still applicable.	smelserw	04/12/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903531	Inspection 708903530 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6507312
708903532	Inspection 708903530 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6507313