

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2024

Submitted Date:

04/07/2024

Document Number:

708903471

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Smelser, Wayne _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 24 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465894	GAS COMPRESSOR STATION	AC			-	CS_Webster	AC

General Comment:

[CECMC Inspection Report Summary](#)
On 04/03/2024 at approximately 10:47 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Webster Compressor Station. Facility # 465894 in Garfield County Colorado. Location is within High Priority/Density Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Tank battery lacks required signage with a CA date of 05/07/2024
2. Signs/Marker - Some required info on antifreeze tank is illegible with a CA date of 05/07/2024
3. Housekeeping - Compressor line lacks wildlife protection/wildlife hazard/available for entry by wildlife & Openings on vessel available for entry by wildlife/wildlife hazards with a CA date of 04/14/2024
4. Equipment - Open ended load line with a CA date of 04/14/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Some required info on antifreeze tank is illegible		
Corrective Action:	Comply with CECMC tank labeling rules	Date:	05/07/2024
Type	BATTERY		
Comment:	Tank battery lacks required signage		
Corrective Action:	Comply with CECMC tank battery signage rules	Date:	05/07/2024
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Small amount of stained soils & gravel near 1 compressor		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Openings on vessel available for entry by wildlife/wildlife hazards & compressor line lacks wildlife protection/wildlife hazard/available for entry by wildlife		
Corrective Action:	Comply with CECMC wildlife rules	Date:	04/14/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	6ft security fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Spill response station		
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Valve on ECD line is shut & auto ignitor is disconnected & laying on the ground		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	All load lines will be capped or plugged	Date:	04/14/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Antifreeze
Other (Capacity)	500 gal
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,

Comment:	Tank not equipped with telemetry	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: Separate containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)	Compressor engine oil	
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment: Separate containment				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 465894 Type: GAS API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Check Dams						Some BMP's may need maintenance in the near future
Waddles						
Compaction						Small amount of light compaction
Gravel						Sparse to none in some areas
Ditches						
		Gravel				Sparse to none in sections
		Culverts				
		Compaction				
				Material Handling And Spill Prevention		Chemical tank containment
Rip Rap						

Comment: Some check dams on location are starting to show some signs of erosion &/or sediment buildup & may need maintenance in the near future.

Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker, Housekeeping & Equipment for observed compliance issues.	smelserw	04/07/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403745493	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6498792
708903472	Inspection 708903471 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6498790
708903473	Inspection 708903471 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6498791