

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2024

Submitted Date:

04/14/2024

Document Number:

708903552

FIELD INSPECTION FORM

Loc ID 335108 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

26 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282178	WELL	PR	12/22/2005	GW	045-11694	CLOUGH RWF 311-22	PR
282179	WELL	PR	09/14/2006	GW	045-11693	CLOUGH RWF 421-22	PR
282180	WELL	PR	02/13/2007	GW	045-11692	CLOUGH RWF 321-22	PR
282181	WELL	PR	09/15/2006	GW	045-11691	CLOUGH RWF 411-22	PR
282253	WELL	PR	12/28/2005	GW	045-11709	CLOUGH RWF 521-22	PR
282254	WELL	PR	12/28/2005	GW	045-11708	CLOUGH RWF 511-22	PR
282265	WELL	PR	09/15/2006	GW	045-11698	CLOUGH RWF 412-22	PR
282267	WELL	SI	08/01/2023	GW	045-11697	CLOUGH RWF 312-22	SI

General Comment:

[CECMC Inspection Report Summary](#)
On 04/10/2024 at approximately 13:59 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad. Location # 335108 in Garfield County Colorado.
Please refer to inspection 708903357 conducted on 03/20/2024, previous corrective actions have been completed. Location is within High Priority/Density Habitat areas. While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/Remote locations - Shared facilities with the CLOUGH 115 pad, location # 335215 & the CLOUGH RMV 153-22 pad, location # 324187

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery sign weathered & fading but still legible at this time		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Some wellhead signs weathered & cracking but still legible at this time		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Liquid nitrogen tank - hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 11		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	RWF 312-22, 421-22 & 511-22 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible. Remaing 5 wells have no form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	282178	Type:	WELL	API Number:	045-11694	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	282179	Type:	WELL	API Number:	045-11693	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	282180	Type:	WELL	API Number:	045-11692	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	282181	Type:	WELL	API Number:	045-11691	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	282253	Type:	WELL	API Number:	045-11709	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	282254	Type:	WELL	API Number:	045-11708	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	282265	Type:	WELL	API Number:	045-11698	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										
Facility ID:	282267	Type:	WELL	API Number:	045-11697	Status:	SI	Insp. Status:	SI	
Producing Well										
Comment:	Producing, well on plunger lift									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12										

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Compaction				
		Culverts				
Waddles						
Check Dams						
Gravel						Sparse to none in areas
		Gravel				Sparse to none in sections
		Ditches				
Compaction						Light compaction in some areas

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Split pad/Remote locations - Shared facilities with the CLOUGH 115 pad, location # 335215 & the CLOUGH RMV 153-22 pad, location # 324187	smelserw	04/14/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903553	Inspection 708903552 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6507718
708903554	Inspection 708903552 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6507719