

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/15/2024

Document Number:

708302032

FIELD INSPECTION FORM

Loc ID 336047 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CHEVRON		atlx@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276275	WELL	PR	12/15/2005	GW	045-10434	SKINNER RIDGE 598-25-3	PR
293971	WELL	PR	11/22/2009	GW	045-15182	SKR 598-25-AV-01	PR
293972	WELL	PR	11/20/2009	GW	045-15183	SKR 598-25-AV-03	PR
293973	WELL	PR	11/14/2009	GW	045-15184	SKR 598-25-AV-05	PR
293974	WELL	PR	08/30/2013	GW	045-15185	SKR 598-25-AV-06	PR
293975	WELL	PR	10/11/2009	GW	045-15186	SKR 598-25-AV-02	PR
293976	WELL	PR	08/30/2013	GW	045-15187	SKR 598-25-AV-11	PR
293977	WELL	PR	10/08/2009	GW	045-15188	SKR 598-25-AV-04	PR
293978	WELL	PR	09/01/2020	GW	045-15189	SKR 598-25-AV-08	PR
293979	WELL	PR	12/08/2009	GW	045-15190	SKR 598-25-AV-14	PR
293980	WELL	PR	11/17/2009	GW	045-15191	SKR 598-25-AV-07	PR
293981	WELL	PR	02/01/2011	GW	045-15192	SKR 598-25-AV-15	PR
293982	WELL	PR	08/15/2012	GW	045-15193	SKR 598-25-AV-13	PR
293985	WELL	PR	11/07/2009	GW	045-15195	SKR 598-25-AV-09	PR
293990	WELL	PR	09/30/2009	GW	045-15196	SKR 598-25-AV-10	PR
293993	WELL	PR	12/08/2009	GW	045-15197	SKR 598-25-AV-12	PR
294087	WELL	PR	08/01/2013	GW	045-15243	SKR 598-25-AV-20	PR
294110	WELL	PR	05/01/2019	GW	045-15254	SKR 598-25-AV 19	PR
294112	WELL	PR	02/01/2011	GW	045-15255	SKR 598-25-AV-21	PR
294113	WELL	PR	08/30/2013	GW	045-15256	SKR 598-25-AV-16	PR
294114	WELL	PR	08/30/2013	GW	045-15257	SKR 598-25-AV-22	PR
294116	WELL	PR	02/09/2010	GW	045-15258	SKR 598-25-AV-18	PR

294117	WELL	PR	06/01/2023	GW	045-15259	SKR 598-25-AV-17	PR
--------	------	----	------------	----	-----------	------------------	----

General Comment:

[COGCC Inspection Report Summary](#)

On 4/11/2024 at approximately 12:35, Compliance Inspector Matthew Morris conducted an on-site inspection at CHEVRON USA INC, SKINNER RIDGE-65S98W/25NENW at Location ID #336047 in Garfield County, Colorado.

Normal production operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#		corrective date
Type: Bradenhead		# 3		
Comment:				
Corrective Action:			Date:	
Type: Other		#		
Comment:	Separator housing			
Corrective Action:			Date:	
Type: Plunger Lift		# 3		
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift		# 20		
Comment:				
Corrective Action:			Date:	
Type: Bradenhead		# 20		
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors		# 3		
Comment:				

Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Line heaters (out of service)		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	276275	Type:	WELL	API Number:	045-10434	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293971	Type:	WELL	API Number:	045-15182	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293972	Type:	WELL	API Number:	045-15183	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293973	Type:	WELL	API Number:	045-15184	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293974	Type:	WELL	API Number:	045-15185	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293975	Type:	WELL	API Number:	045-15186	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293976	Type:	WELL	API Number:	045-15187	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	293977	Type:	WELL	API Number:	045-15188	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293978 Type: WELL API Number: 045-15189 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293979 Type: WELL API Number: 045-15190 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293980 Type: WELL API Number: 045-15191 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293981 Type: WELL API Number: 045-15192 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293982 Type: WELL API Number: 045-15193 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293985 Type: WELL API Number: 045-15195 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293990 Type: WELL API Number: 045-15196 Status: PR Insp. Status: PR

Producing Well			
Comment:			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	293993	Type:	WELL
API Number:	045-15197	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294087	Type:	WELL
API Number:	045-15243	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294110	Type:	WELL
API Number:	045-15254	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294112	Type:	WELL
API Number:	045-15255	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294113	Type:	WELL
API Number:	045-15256	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294114	Type:	WELL
API Number:	045-15257	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	294116	Type:	WELL
API Number:	045-15258	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:			
Corrective Action:		Date:	

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Compaction				
		Gravel				
		Check Dams				
		Culverts				
Compaction						
Berms						
		Ditches				
				Material Handling And Spill Prevention		Chemical tanks in secondary containment

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302033	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6508640