

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2024

Submitted Date:

04/15/2024

Document Number:

702403358

FIELD INSPECTION FORMLoc ID 474767 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

39 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477665	WELL	PR	06/25/2022	OW	123-51164	County Line 3130-04H	PR
477667	WELL	PR	08/16/2022	OW	123-51166	County Line 3107-05H	PR
477668	WELL	PR	09/04/2022	OW	123-51167	County Line 3107-09H	PR
477669	WELL	PR	08/01/2022	OW	123-51168	County Line 3112-03H	PR
477670	WELL	PR	06/27/2022	OW	123-51169	County Line 3130-01H	PR
477671	WELL	PR	08/27/2022	OW	123-51170	County Line 3107-11H	PR
477672	WELL	PR	08/01/2022	OW	123-51171	County Line 3112-01H	PR
477673	WELL	PR	07/01/2022	OW	123-51172	County Line 3107-06H	PR
477674	WELL	PR	09/03/2022	OW	123-51173	County Line 3107-08H	PR
477675	WELL	PR	08/28/2022	OW	123-51174	County Line 3107-12H	PR
477676	WELL	PR	08/07/2022	OW	123-51175	County Line 3107-10H	PR
477677	WELL	PR	06/28/2022	OW	123-51176	County Line 3130-06H	PR
477678	WELL	PR	06/29/2022	OW	123-51177	County Line 3130-05H	PR
477679	WELL	PR	12/01/2023	OW	123-51178	County Line 3112-02H	PR
477680	WELL	PR	07/01/2022	OW	123-51179	County Line 3107-07H	PR
477681	WELL	PR	06/27/2022	OW	123-51180	County Line 3130-02H	PR
477682	WELL	PR	07/01/2023	OW	123-51181	County Line 3112-04H	PR

General Comment:

This is a Multiwell pad inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type			
Comment:	Some of the well cellars have trash & debris and will need to be addressed when construction & fracking operations allow.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound walls on 4 sides		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 17		
Comment:	automation		
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 17		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 477665 Type: WELL API Number: 123-51164 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/21/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477667 Type: WELL API Number: 123-51166 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/21/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477668 Type: WELL API Number: 123-51167 Status: PR Insp. Status: PR**BradenHead**Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477669 Type: WELL API Number: 123-51168 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477670 Type: WELL API Number: 123-51169 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477671 Type: WELL API Number: 123-51170 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477672 Type: WELL API Number: 123-51171 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477673 Type: WELL API Number: 123-51172 Status: PR Insp. Status: PR

Producing Well

Comment: Plumbed to surface

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477674 Type: WELL API Number: 123-51173 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477675 Type: WELL API Number: 123-51174 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead			
Date of Last Brhd Test: 11/21/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: Plumbed to surface			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477676	Type: WELL	API Number: 123-51175	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 11/21/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: Plumbed to surface			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477677	Type: WELL	API Number: 123-51176	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 11/21/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: Plumbed to surface			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477678	Type: WELL	API Number: 123-51177	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR			
Corrective Action:		Date:	

--	--	--	--

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477679 Type: WELL API Number: 123-51178 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477680 Type: WELL API Number: 123-51179 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477681 Type: WELL API Number: 123-51180 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
This is a Routine Field Inspection on PR wells in addition to setting up a sound study. Any Corrective Actions from previous inspections not addressed are still applicable. The location has active construction work going on in preparation to frack the remaining wells and bring them into PR when Fracking operations are complete.	revasr	04/15/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403359	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6509170