

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2024

Submitted Date:

04/15/2024

Document Number:

707602535

FIELD INSPECTION FORMLoc ID 428637 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430337	TANK BATTERY	AC	03/13/2012		-	Siebring Pad 5-63-32-16H	IO

General Comment:

This is a Tank Battery inspection.

Well(s): 4: Shut-In | SI.

Battery: Inactive | Shut-down. (North tank battery).

These wells are associated with North tank battery.

Centralized Battery serves 2 Location IDs

(428174, 428637).

(Well(s): 4: Shut-In).

Centralized Battery serves 1 Tank Battery Facility ID

(430337).

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707602533 and/or Location ID #428174 for SI Well(s) info.

B.) Field Inspection Report doc. #707602535 and/or Facility ID #430337 for Battery / Facility, Equipment info.

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	OOSLAT applied at Battery equipment.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 10		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	Crude, produced H2O storage, Facility vapor line combustor(s). Controls crude oil, produced H2O tank(s), Facility vapors. Pilots: OFF Shut-down.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	<p>1: Gas Sales Master: Calibration card(s) indicates calibration <= 1 year. (DCP). Last calibration: 02/14/2024. Inactive.</p> <p>4: Gas Sales Allocation: Calibration card(s) indicates calibration <= 1 year. Last calibration: 03/12/2024. Inactive.</p>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	<p>Battery site: 1: ECD scrubber(s). 1: Storage bldg. 4: Tank heaters. Inactive. Labeled: "Not in use".</p>		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	<p>Centralized Battery serves 2 Location IDs (428174, 428637). (Well(s): 4: Shut-In).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (430337).</p>				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Evins, Bret

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s).				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	500 BBLs	STEEL AST		40.362704,-104.450944
Comment:	Equalizer line(s) connect crude oil tank(s). 7 of 8 crude oil tank(s): Insulated.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s).			
Corrective Action:				Date:

Wells Served By Facilities Above**AirsID**

API Number
123-35263
123-35261
123-35268
123-35260

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	430337	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	IO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
CECMC Inspection Report Synopsis: On THU 04/11/2024 at approximately 14:17 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Facility Name: Siebring Pad/5-63-32-16H Facility ID: 430337 Location Name: Siebring/5-63-32 NE Location ID: 428637 Well Name(s): Siebring 5-63-32-16H, Siebring 5-63-32-17H, Siebring 5-63-32-32H, Siebring 5-63-32-48H. API: 123-35268, 123-35261, 123-35260, 123-35263. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm. While there, I observed: Well(s): 4: Shut-In SI. Battery: Inactive Shut-down. (North tank battery). These wells are associated with North tank battery. Routine inspection. *Any Corrective Actions from prior inspections that have not been addressed remain applicable.	evinsb	04/15/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602536	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6509321