

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2024

Submitted Date:

04/10/2024

Document Number:

699505686

FIELD INSPECTION FORMLoc ID 432153 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| , | | Inspections@civiresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 432151 | WELL | PR | 04/01/2023 | OW | 123-36974 | MATHEWS 4B-14H | PR |
| 432152 | WELL | PR | 08/01/2023 | OW | 123-36975 | MATHEWS 4A-14H | PR |
| 432154 | WELL | PR | 10/01/2019 | OW | 123-36976 | MATHEWS 4C-14H | PR |

General Comment:

There have been no changes to equipment on location since previous inspection.

| | | | | | |
|--|------|--------|--|-------|-------------|
| Location | | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Emergency Contact Number: | | | | | |
| Comment: | | | | | Date: _____ |
| Corrective Action: | | | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Inspected Facilities

Facility ID: 432151 Type: WELL API Number: 123-36974 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432152 Type: WELL API Number: 123-36975 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432154 Type: WELL API Number: 123-36976 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/19/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

At time of inspection location appears to be in compliance with ECMC rules.

At time of inspection weather conditions were partly cloudy, warm, calm.

medinaj

04/10/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 699505687 | inspection pictures | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6509808 |