

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2024

Submitted Date:

04/16/2024

Document Number:

714200942**FIELD INSPECTION FORM**Loc ID 420254 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420271	WELL	PR	08/01/2020	GW	123-32531	Betz PC G10-33D	PR

General Comment:[THIS IS A FOLLOW UP INSPECTION.](#)

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	one tank does not contain sign for contents.			
Corrective Action:	Comply with Rule 605.h.			Date: 04/26/2024
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: <input type="text"/>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: <input type="text"/>

Inspected Facilities									
Facility ID:	420271	Type:	WELL	API Number:	123-32531	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR (previous inspection)								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200849 AND IN REPONSE TO FIRR DOC#: 403740986. It appears the previous corrective actions assigned to this location have not been resolved. One tank appears to not have the contents displayed on the tank. The pervious corrective action assignnd to this location still remains in effect with its original corrective action date. For additional information please refer to previous inspection DOC#: 714200849 or FIRR DOC#: 403740986.	santistb	04/16/2024