

## Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 14-2 (B14W) Pad

Location ID: 334742



Photo # 4183 From entrance to location



Photo # 4184 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 14-2 (B14W) Pad

Location ID: 334742



Photo # 4185 Location



Photo # 4186 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 14-2 (B14W) Pad

Location ID: 334742



**Photo # 4187 Location**



**Photo # 4188 Possible tank failure – tank appears to be compromised, holes & corrosion on the top of production tank**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 14-2 (B14W) Pad

Location ID: 334742



**Photo # 4189 Possible tank failure – tank appears to be compromised, holes & corrosion on the top of tank**



**Photo # 4190 Possible tank failure – tank appears to be compromised, holes & corrosion on the top of tank**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 14-2 (B14W) Pad

Location ID: 334742



**Photo # 4191 Possible tank failure – tank appears to be compromised, holes & corrosion on the top of tank**



**Photo # 4192 Possible tank failure – tank appears to be compromised, holes & corrosion on the top of tank**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 14-2 (B14W) Pad

Location ID: 334742



**Photo # 4193 Hole in liner/liner needs maintenance**



**Photo # 4194 Hole in liner/liner needs maintenance**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 14-2 (B14W) Pad

Location ID: 334742



**Photo # 4195 Hole in liner/liner needs maintenance**



**Photo # 4196 Hole in liner/liner needs maintenance**