

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
04/11/2024
Submitted Date:
04/16/2024
Document Number:
707602541

FIELD INSPECTION FORM

Loc ID 332237 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
ECMC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271412	WELL	TA	10/14/2021	GW	123-22021	SIEBRING 41-32	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).
(Well(s): 5: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602541 and/or Location ID #332237 for TA Well(s) info.
B.) Field Inspection Report doc. #707602543 and/or Location ID #306088 for TA Well(s) info.
C.) Field Inspection Report doc. #707602545 and/or Location ID #332148 for TA Well(s) info.
D.) Field Inspection Report doc. #707602547 and/or Location ID #332236 for TA Well(s) info.
E.) Field Inspection Report doc. #707602549 and/or Location ID #332267 for TA Well(s) info.
F.) Field Inspection Report doc. #707602551 and/or Location ID #332237 for Battery / Facility, Equipment info.

Location

Lease Road:			
	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.363010,-104.450910
Comment:	Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). (Well(s): 5: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 271412 Type: WELL API Number: 123-22021 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Shut-In | SI.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
CECMC records last production: 10/2020.

Form 5A on file. TA date: 09/15/2021. Approved.
DH-CIBP set.
Form 21-MIT on file. MIT date: 09/23/2021. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 01/04/2021. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 06/01/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 04/11/2024 at approximately 15:27 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: SIEBRING/41-32 Location ID: 332237 Well Name(s): Siebring 41-32. API: 123-22021. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/16/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602542	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511286