

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2024

Submitted Date:

04/16/2024

Document Number:

707602545

FIELD INSPECTION FORMLoc ID 332148 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270569	WELL	TA	11/01/2018	GW	123-21903	SIEBRING 32-32	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs
(332237, 306088, 332148, 332236, 332267).
(Well(s): 5: Temporarily Abandoned | TA).Centralized Battery serves 1 Tank Battery Facility ID
(Pending).

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707602541 and/or Location ID #332237
for TA Well(s) info.B.) Field Inspection Report doc. #707602543 and/or Location ID #306088
for TA Well(s) info.C.) Field Inspection Report doc. #707602545 and/or Location ID #332148
for TA Well(s) info.D.) Field Inspection Report doc. #707602547 and/or Location ID #332236
for TA Well(s) info.E.) Field Inspection Report doc. #707602549 and/or Location ID #332267
for TA Well(s) info.F.) Field Inspection Report doc. #707602551 and/or Location ID #332237
for Battery / Facility, Equipment info.

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.363010,-104.450910
Comment:	Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). (Well(s): 5: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 270569

Type: WELL

API Number: 123-21903

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
CECMC records last production: 05/2017.

Form 5A on file. TA date: 06/01/2017. Approved.
DH-RBP set.
Form 21-MIT on file. MIT date: 10/05/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 01/05/2019. Approved.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/01/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Date:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 04/11/2024 at approximately 15:01 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: SIEBRING-65N63W/32SWNE Location ID: 332148 Well Name(s): Siebring 32-32. API: 123-21903. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/16/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602546	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511288