

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/16/2024

Document Number:

707602551

**FIELD INSPECTION FORM**

Loc ID: 332237  
Inspector Name: Evins, Bret  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332237	LOCATION	AC			-	SIEBRING 41-32	IO

**General Comment:**

This is a BATTERY inspection.  
Well(s): 5: Temporarily Abandoned | TA.  
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).  
(Well(s): 5: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707602541 and/or Location ID #332237 for TA Well(s) info.  
B.) Field Inspection Report doc. #707602543 and/or Location ID #306088 for TA Well(s) info.  
C.) Field Inspection Report doc. #707602545 and/or Location ID #332148 for TA Well(s) info.  
D.) Field Inspection Report doc. #707602547 and/or Location ID #332236 for TA Well(s) info.  
E.) Field Inspection Report doc. #707602549 and/or Location ID #332267 for TA Well(s) info.  
F.) Field Inspection Report doc. #707602551 and/or Location ID #332237 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	OOSLAT applied at Battery equipment.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Methanol. Placards.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	Horizontal Heated Separator	# 4	corrective date
Comment:			
Corrective Action:			Date:
Type:	Gas Meter Run	# 0	
Comment:	Removed.		
Corrective Action:			Date:
Type:	Ancillary equipment	# 1	
Comment:	Battery site: 1: Bulk Methanol tank(s) w/ drip containment. Placards.		
Corrective Action:			Date:

Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). (Well(s): 5: Temporarily Abandoned   TA).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s).			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.363010,-104.450910
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Berms shared w/ crude oil tank(s), produced H2O tank(s).</a>				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
123-22020
123-22062
123-22021
123-23967
123-21903

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 332237 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On THU 04/11/2024 at approximately 14:37 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: HIGHPOINT OPERATING CORPORATION                      Facility Name: Pending                      Facility ID: Pending                      Location Name: SIEBRING/41-32                      Location ID: 332237                      Well Name(s):                      Siebring 41-32, Siebring 31-32, Siebring 32-32, Siebring 42-32, Siebring CNE-32.                      API:                      123-22021, 123-22062, 123-21903, 123-22020, 123-23967.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 5: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/16/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602552	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6511291</a>