

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2024

Submitted Date:

04/10/2024

Document Number:

708903508

FIELD INSPECTION FORMLoc ID 323785 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------|
| , Mustang | | nwelch@vaqueroenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 210803 | WELL | PR | 10/01/2023 | GW | 045-06561 | YOUBERG 23-24-6S-94W | PR |

General Comment:**CECMC Inspection Report Summary**

On 04/08/2024 at approximately 12:42 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at MUSTANG RESOURCES LLC YOUBERG 23-24-6S-94W Pad.

Location # 323785 in Garfield County Colorado.

Please refer to inspection 708901775 conducted on 09/22/2023, previous corrective actions have been completed.

Location is within High Priority/Density/Black Bear/NSO Habitat areas & Bald Eagle Roost site.

Location is approximately 104 yards from Beaver Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Meter not calibrated annually/not in compliance with CECMC rules with a CA date of 05/10/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

| | | | |
|--------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|-----------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | No tank battery | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|------------------|-------|--|
| Comment: | 911/888-291-8588 | | |
| Corrective Action: | | Date: | |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbed wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------------|---|-------|-----------------|
| | | | corrective date |
| Type: Deadman # & Marked | # 1 | | |
| Comment: | Marked | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter not calibrated annually/not in compliance with CECMC rules (please refer to photo log, last meter calibration 2021) | | |
| Corrective Action: | Comply with CECMC gas meter calibration rules | Date: | 05/10/2024 |
| Type: Plunger Lift | # 0 | | |
| Comment: | Well not on plunger lift | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|-------------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 210803 | Type: | WELL | API Number: | 045-06561 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing, well not on plunger lift | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|-----------------------|
| Compaction | | | | | | Some light compaction |
| Gravel | | | | | | Sparse to none |
| | | Gravel | | | | Sparse to none |
| | | Compaction | | | | |

Comment: No other observed BMP's

Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

| Comment | User | Date |
|--|----------|------------|
| Please refer to Equipment for observed compliance issue. | smelserw | 04/10/2024 |
| As to the domestic tap & PRV corrective actions from the previous inspection (inspection 708901775) according to operator (Mustang), the domestic tap is not connected to their well & belongs to TEP. CECMC Integrity Engineering Technician Mike Longworth contacted TEP & was informed by Chuck Smith that the Mustang well use to supply gas to nearby a house until it started to not be able to keep up. Then TEP ran a line from their nearby location to the tap in the meter house. Please refer to inspection 701103834 conducted on 09/27/2023 for more info on TEP domestic tap. | | |

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 403750158 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503821 |
| 708903509 | Inspection 708903508 Stormwater photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503819 |
| 708903510 | Inspection 708903508 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503820 |