

Inspection Photos

April 12th, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 334049

Inspection Document #: 714000664

Archuleta County, CO

Township: NWNE 23 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Chapin 32-06 23-3, 4
Location ID: 334049

4/12/24
+37.006769,-107.466503
35° NE



Photo 1. View of the well disturbance from the access point facing center.

Inspection Photos
Location Name: Chapin 32-06 23-3, 4
Location ID: 334049



Photo 2. southern fill slope/interim reclamation areas dominated by kochia/russian thistle debris and lacking vegetation. Stormwater BMPs/soil stabilization is needed until long term stabilization is achieved with perennial vegetation.

Inspection Photos
Location Name: Chapin 32-06 23-3, 4
Location ID: 334049



4/12/24
+37.007154,-107.466102
351° N

Photo 3. Unused oil and gas fitting/piping equipment observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06259

Inspection Photos
Location Name: Chapin 32-06 23-3, 4
Location ID: 334049



Photo 4. View of weedy kochia and russian thistle debris dominating the entire disturbance.

Inspection Photos
Location Name: Chapin 32-06 23-3, 4
Location ID: 334049



Photo 5. View of weedy kochia/russian thistle debris on location.



Inspection Photos
Location Name: Chapin 32-06 23-3, 4
Location ID: 334049



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Rutting observed on location, additional stabilization is needed to minimize site degradation.

API #: 007-06259

Inspection Photos
Location Name: Chapin 32-06 23-3, 4
Location ID: 334049



4/12/24
+37.006680,-107.466445
142° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area comprised of smooth brome and intermediate wheatgrass.

API #: 007-06259