

# Inspection Photos

April 12th, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 334035

Inspection Document #: 714000676

La Plata County, CO

Township: SWSE 15 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Quintana 32-6 15-2, 4  
Location ID: 334035

4/12/24  
+37.011097,-107.485598  
293° NW



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos

Location Name: Quintana 32-6 15-2, 4

Location ID: 334035



Photo 2. View of unmarked guy line anchor on location.



Inspection Photos  
Location Name: Quintana 32-6 15-2, 4  
Location ID: 334035

4/12/24  
+37.011021,-107.485616  
240° SW



**Photo 3.** View of an un stabilized southern cut slope/interim reclamation area. Erosion controls need to be installed until area is stabilized with perennial vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-09493, 09096

Inspection Photos

Location Name: Quintana 32-6 15-2, 4

Location ID: 334035



**Photo 4.** View of various piles of wattles in the southern portion of the disturbance that are no longer functioning and are considered debris.

Inspection Photos

Location Name: Quintana 32-6 15-2, 4

Location ID: 334035



**Photo 5.** Gully erosion observed forming in the southern cut slope where soils remain unstabilized.

Inspection Photos

Location Name: Quintana 32-6 15-2, 4

Location ID: 334035



**Photo 6.** View of storm water culvert on location that is full of sediment and no longer functioning.

Inspection Photos

Location Name: Quintana 32-6 15-2, 4

Location ID: 334035



4/12/24

+37.010758,-107.485342

99° E



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 7.** Reference area comprised of sage brush, intermediate wheatgrass and rabbit brush.

API #: 067-09493, 09096