

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2024

Submitted Date:

04/17/2024

Document Number:

707602556

FIELD INSPECTION FORM

Loc ID 332268 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10071
 Name of Operator: HIGHPOINT OPERATING CORPORATION
 Address: 555 17TH ST STE 3700
 City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271460	WELL	TA	07/11/2017	GW	123-22064	VAN WYKE 22-32	TA

General Comment:

This is a WELL inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (332695, 332268).
 (Well(s): 3: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
 A.) Field Inspection Report doc. #707602553 and/or Location ID #332695 for TA Well(s) info.
 B.) Field Inspection Report doc. #707602556 and/or Location ID #332268 for TA Well(s) info.
 C.) Field Inspection Report doc. #707602558 and/or Location ID #332695 for Battery / Facility, Equipment info.

Location

Lease Road:

	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.362840,-104.463810
Comment:	Centralized Battery serves 2 Location IDs (332695, 332268). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 271460 Type: WELL API Number: 123-22064 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
CECMC records last production: 10/2016.

Form 5A on file. TA date: 05/31/2017. Approved.
DH-RBP set.
Form 21-MIT on file. MIT date: 11/08/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 11/15/2016. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 06/15/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 04/12/2024 at approximately 14:54 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: VAN WYKE-65N63W/32SEW Location ID: 332268 Well Name(s): Van Wyke 22-32. API: 123-22064. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602557	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6512301