

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2024

Submitted Date:

04/17/2024

Document Number:

696205754

FIELD INSPECTION FORM

Loc ID: 335054 Inspector Name: Trujillo, Aaron On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 13 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspectionReports@terraep.com	TEP
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335054	LOCATION	AC			-	CSF-67S91W 8SESW	RI

General Comment:

On 4/12/2024, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at TEP Rocky Mountain LLC's CSF-67S91W/8SESW Location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Stormwater
- Loadlines missing cap/plug
- Tank Battery Signage
- Weeds

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	<p>It was observed in this inspection that the Operator (name) information at battery signage has partially torn off. Additional information pursuant to Rule 605.e (Telephone number at which the Operator can be reached at all times; C. Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; E. Well name(s) and API number(s) associated with the Tank battery) not posted at sign, or not legible.</p> <p>Additionally, the emergency contact number (1-855-625-9922) is no longer in service.</p>		
Corrective Action:	Comply with Rule 605.e	Date:	05/17/2024

Emergency Contact Number:

Comment:	970-285-9377		
	<p>Inspector tested the emergency number (1-855-625-9922) posted at battery. Emergency number is no longer in service, and appears to have been the emergency line for the previous Operator. See "Battery" above.</p>		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	4 strand fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock Panels		
Corrective Action:		Date:	

Equipment:

Type:	#		corrective date
-------	---	--	-----------------

Comment:	Lines at tanks observed missing required cap/plug.		
Corrective Action:	Comply with Rule 603.i	Date:	04/24/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 335054 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment No waste or debris observed on the interim or production areas of the Location.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment No unused or unneeded equipment observed on the interim or production areas of the Location.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment Only one anchor observed (west end of pad). Unsure if all other anchors have been removed, or lack required marking.

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? In Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? I

Comment No immediate reclamation concerns observed at time of inspection; areas appear to be progressing towards ECMC 1003 Standards.

A small patch of Common mullein was observed within the interim slopes on the north end of the Location.

Corrective Action Continue to monitor and manage weeds on the Location in accordance with Rule 1003.f and Rule 606.c Date 06/30/2024

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: _____	Date _____
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/>
	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed in this inspection that stormwater and erosion control BMPs to manage runoff from the working pad surface are missing or insufficient; runoff from the pad is resulting in sediment deposition and degradation to the interim areas on the east and northern ends of the Location. Ditch along the western perimeter appears to discharge directly into the interim areas, and travel straight down the slope; BMPs in conjunction with the ditch to interrupt velocity or to allow sediment fallout prior to off-site stormwater discharge not apparent.

Corrective Action: Comply with Rule 1002.f- install or repair required stormwater and erosion control measures to manage runoff from the pad in a manner that minimizes erosion, degradation and sediment transport. Ensure BMPs are installed per good engineering practice, and maintained in a proper functioning condition.

Date: 04/19/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696205756	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6512376