

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2024

Submitted Date:

04/17/2024

Document Number:

702403372

FIELD INSPECTION FORM

Loc ID 336477 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
 Address: 555 17TH STREET SUITE 3700
 City: DENVER State: CO Zip: 80202

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261855	WELL	SI	11/01/2022	GW	123-20653	DIER 14-8	SI
261856	WELL	SI	12/01/2022	GW	123-20652	DIER 13-8	SI

General Comment:

[This is a Multi-well pad & tank battery inspection.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	IGNITOR/COMBUSTOR		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag panel x 2		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	automation & telemetry		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card indicates current calibration. Wellsite Services		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.149470,-104.920310
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	150 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	shares containment with crud tanl				
Corrective Action:				Date:	

Wells Served By Facilities Above

AirsID

API Number
123-20653
123-20652

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 261855 Type: WELL API Number: 123-20653 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI & on the inactive well list, Form 06A Doc # 403213985.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: exposed at surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 261856 Type: WELL API Number: 123-20652 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI & on the inactive well list, Form 06A Doc #403451136

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
This is a Routine Field Inspection. Any Corrective Actions from previous inspections not addressed are still applicable.	revasr	04/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403373	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6512666