

Final Reclamation and Stormwater Inspection

Date: 04/17/2024

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - 8960

Location ID: 302895

Inspection Document #: 708201160

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pronghorn 31-21
Location ID: 302895



Photo 1. It appears the location has been recently reclaimed with evidence of straw mulch and germination observed during this inspection. A follow-up inspection will be conducted at a later date to verify vegetative compliance with Rule 1004.

Inspection Photos
Location Name: Pronghorn 31-21
Location ID: 302895



Photo 2. Taken near the northern portion of the location, facing south. See comments in Photo 1.

Inspection Photos
Location Name: Pronghorn 31-21
Location ID: 302895



Photo 3. Taken near the center portion of the location, facing west. See comments in Photo 1.

Inspection Photos
Location Name: Pronghorn 31-21
Location ID: 302895



Photo 4. Taken near the center portion of the location, facing north. See comments in Photo 1.

Inspection Photos
Location Name: Pronghorn 31-21
Location ID: 302895



Photo 5. Taken near the center portion of the location, facing east. See comments in Photo 1.

Inspection Photos
Location Name: Pronghorn 31-21
Location ID: 302895



Photo 6. Taken along the access road, facing south. See comments in Photo 1.