

Inspection Photos

API: 055-06037

Operator: OXY USA INC

Inspection Date: 4/16/2024

County: HUERFANO



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. The perimeter fence around the location is not maintained and there are posts and wire laying on the ground.



Inspection Photos



Photo 3. The perimeter fence around the location is not maintained and there is wire laying on the ground.



Inspection Photos



Photo 4. This is an example at a nearby fenceline and the importance to either maintain or remove fences. CPW wildlife friendly fencing is encouraged.

