

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
04/18/2024
Submitted Date:
04/18/2024
Document Number:
695109463

FIELD INSPECTION FORM

Loc ID 307592 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217874	WELL	PR	11/22/1999	CBM	071-06653	LORENCITO 2-9-34-66	PR

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Gas Meter Run	# 1	
Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:
Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Ancillary equipment	# 1	
Comment:		
Corrective Action:		Date:
Bradenhead	# 1	
Comment: IS ACCESSABLE		
Corrective Action:		Date:
Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 119925 Lat: 37.102785 Long: -104.780564

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: NO

Comment: **PHOTO 4: FLUID LEVEL IN PRODUCED WATER PIT IS ABOVE FREEBOARD (SPOKE WITH EVERGREEN PRODUCTION FOREMAN ED ROMERO).
PHOTO 5: THE SALT/MINERAL DEPOSIT RING AROUND THE PIT INDICATES THAT THE PIT IS BEEING MAINTAINED ABOVE 2' FREEBOARD ON A REGULAR BASES, THE RULE STATES THAT THERE MUST BE A MINIMUM OF 2' FREEBOARD AT ALL TIMES. THIS MEANS THAT THE PIT MUST BE PULLED/DRAINED BEFORE FLUID LEVEL REACHES THE 2' FREEBOARD.**

Corrective Action

Lower fluid level so at least two feet of freeboard exists per Rule 909.c.

Date: 04/19/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695109464	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6516597