

Interim Reclamation and Stormwater Inspection

Date: 4/4/24

Operator: Highpoint Operating Corporation - 10071

Location ID: 437854

Inspection Document #: 713900536

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33

NWNW

Location ID: 437854



ECMC
111° E
4/4/24, 1:47 PM



ECMC
142° SE
4/4/24, 1:56 PM

Photo 1. The photo was taken at the entrance to the well location facing East. The photo illustrates the entrance and operator signage.

Photo 2. The photo was taken at the well location facing Southeast. The photo illustrates the portions of the interim reclamation areas are dominated by Russian thistles.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33

NWNW

Location ID: 437854



Photo 3. The photo was taken at the well location facing North. The photo illustrates the interim area to the East is primarily dominated by Russian thistle.



Photo 4. The photo was taken at the well location facing Northwest. The photo illustrates an unmarked un-tagged riser.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33

NWNW

Location ID: 437854



Photo 5. The photo was taken at the well location facing East. The photo illustrates debris consisting of electrical wires on the production pad.



Photo 6. The photo was taken at the well location facing North. The photo illustrates interim areas in the Northeast of the disturbance are dominated by Russian thistle.

Note - Newly germinating vegetation appears to also be dominated by Russian thistle.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33

NWNW

Location ID: 437854



Photo 5. The photo was taken at the well location facing Southeast. The photo illustrates piping being stored in the interim areas on the East side of the location.



Photo 6. The photo was taken at the well location facing Northwest. The photo illustrates stained soil as well as loadout hoses being stored without any containment.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33

NWNW

Location ID: 437854



Photo 5. The photo was taken at the well location facing Northeast. The photo illustrates stained soil within the secondary containment.

Note - Recent precipitation has occurred as well.



Photo 6. The photo was taken at the well location facing East. The photo illustrates tumbleweeds stuck within equipment.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33

NWNW

Location ID: 437854



Photo 5. The photo was taken at the well location facing West. The photo illustrates stained soil around a buried condensate container.



Photo 6. The photo was taken at the well location facing Southwest. The photo illustrates a shipping container being stored on the production pad.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33

NWNW

Location ID: 437854



Photo 5. The reference photo was taken at the edge of the well location facing East. The photo illustrates that reference areas are dominated by Sand dropseed and Yucca.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Number: 713900536