

# Inspection Photos

April 18th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325959

Inspection Document #: 714000688

La Plata County, CO

Township: NWNE 21 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Allison Unit 137  
Location ID: 325959

4/18/24  
+37.006539,-107.511303  
310° NW



**Photo 1.** View of the well disturbance taken from the access point facing center.



Inspection Photos  
Location Name: Allison Unit 137  
Location ID: 325959



**Photo 2.** Plastic/metal trash observed within the sounds walls on location.



Inspection Photos  
Location Name: Allison Unit 137  
Location ID: 325959



**Photo 3.** Unused fitting and tubing equipment observed within the produced water tank berm on location.



Inspection Photos  
Location Name: Allison Unit 137  
Location ID: 325959

4/18/24  
+37.006868,-107.511223  
144° SE



**Photo 4.** View of weedy russian thistle debris lining the eastern edge of the disturbance.



Inspection Photos  
Location Name: Allison Unit 137  
Location ID: 325959





Inspection Photos  
Location Name: Allison Unit 137  
Location ID: 325959



**Photo 6.** Impacted surface material observed at the well head.



Inspection Photos  
Location Name: Allison Unit 137  
Location ID: 325959



**Photo 7.** Unmarked guy line anchor on location.