

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2024

Submitted Date:

04/19/2024

Document Number:

707602564

FIELD INSPECTION FORM

Loc ID 432011 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432011	LOCATION	AC			-	CVR Pad 5-63-32	AO

General Comment:

This is a Battery inspection.
Well(s): 9: Producing | PR ; 2: Shut-In | SI.
Battery: Active.

Centralized Battery serves 2 Location IDs (432011, 449306).
(Well(s): 9: Producing | PR ; 2: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602560 and/or Location ID #432011 for PR / SI Well(s) info.
B.) Field Inspection Report doc. #707602562 and/or Location ID #449306 for PR / SI Well(s) info.
C.) Field Inspection Report doc. #707602564 and/or Location ID #432011 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Battery site: Methanol. Placards.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 95%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Partial iron pipe.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Partial iron pipe.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 16		
Comment:	Battery site: 2: ECD scrubber(s). 1: Electric power bank(s). 1: Instrument Air Unit w/ scrubber. (IAU). 1: Methanol, pump(s), tank(s) w/ drip containment. Placards. 11: Tank heater(s). Shut-down. Not-in-use.		
Corrective Action:			Date:
Type: Compressor	# 0		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 5		
Comment:	3: Crude, produced H2O storage, Facility vapor line combustor(s). Controls crude oil, produced H2O tank(s), Facility vapors. Pilots: ON. 2: Crude, produced H2O storage, Facility vapor line combustor(s). Controls crude oil, produced H2O tank(s), Facility vapors. Pilots: OFF. Inactive. Shut-down. LOTO.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Flare	# 0		
Comment:			
Corrective Action:			Date:
Type: VRT	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: LACT	# 2		
Comment:	Inactive. Not-in-use.		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		

Comment:	<p>Battery site: 2: Gas Sales Master meter(s). Calibration card(s) indicates calibration <= 1 year. Last calibration: 02/28/2024. Active.</p> <p>1: Gas Sales check meter(s). Calibration card(s) indicates calibration <= 1 year. Last calibration: 03/12/2024. Active.</p>		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	
Comment:	<p>Centralized Battery serves 2 Location IDs (432011, 449306). (Well(s): 9: Producing PR ; 2: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p>					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s).					
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	4	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s).			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	400 BBLs	STEEL AST		40.355567,-104.466636
Comment:	Equalizer line(s) connect some crude oil tank(s).				
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms shared w/ crude oil tank(s), produced H2O tank(s).			
Corrective Action:				
				Date:

Wells Served By Facilities Above

API Number
123-37086
123-36897
123-44257
123-37087
123-44256
123-44254
123-36898
123-44255
123-44253
123-36899
123-37085

AirsID

API Number	AirsID
------------	--------

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 432011 Type: LOCATION API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> Date: _____						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p style="color: blue; margin: 0;">CECMC Inspection Report Synopsis:</p> <p style="color: blue; margin: 0;">On FRI 04/12/2024 at approximately 11:42 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Facility Name: Pending Facility ID: Pending Location Name: CVR Pad/5-63-32 Location ID: 432011 Well Name(s): See photo(s) #12 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 5, 6 and/or photo(s) #12 attached to this report. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p style="color: blue; margin: 0;">While there, I observed: Well(s): 9: Producing PR ; 2: Shut-In SI. Battery: Active.</p> <p style="color: blue; margin: 0;">Routine inspection.</p> <p style="color: blue; margin: 0;">*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/19/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602565	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6517034