

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2024

Submitted Date:

04/21/2024

Document Number:

707602572**FIELD INSPECTION FORM**Loc ID 323471 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245285	WELL	PA	03/24/2020	OW	123-13080	PLUMB 4	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
 Well(s): 1: Plugged & Abandoned | PA.  
 Battery: Abandoned. ALL equipment has been removed.  
 Abandoned Battery SE corner GPS coordinates: 40.417041 / -104.586628

Abandoned Centralized Battery formerly served 3 Location IDs  
 (323470, 323469, 323471).  
 (Well(s): 3: Plugged & Abandoned | PA).

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

			corrective date
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 245285 Type: WELL API Number: 123-13080 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On WED 04/17/2024 at approximately 16:05 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: PLUMB-65N64W/7SWNE Location ID: 323471 Well Name(s): Plumb #4. API: 123-13080. Location County: Weld County, Colorado Weather: Partly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.417041 / -104.586628</p> <p><b>WELL STATUS COMMENT:</b> Plugged &amp; Abandoned   PA. Form 6-SRA on file. Plugging, cut/cap date: 03/24/2020. Approved. Plugged &amp; Abandoned   PA well GPS coordinates: 40.415440 / -104.591140</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/21/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602573	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6517922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6517922</a>