

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2024

Submitted Date:

04/21/2024

Document Number:

707602578

FIELD INSPECTION FORM

Loc ID: 483509 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449773	WELL	DG	03/21/2024	LO	123-44514	Braskaland A06-765	DG

General Comment:

This is a DRILLING inspection.
Well(s): 1: Drilling | DG.
New well GPS coordinates: 40.505801 / -104.600489

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Access / Entrance / Location; site safety signage posted.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Adequate		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sound & Gas monitors installed outside at 4 corners of sound walls. Gas monitors installed. Enhanced sound barriers installed. Low profile lighting installed for after dusk operations.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Sound walls on 4 sides of location.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 449773 Type: WELL API Number: 123-44514 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Patterson UTI 268 Pusher/Rig Manager: Dave Nielsen
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: Waste Management LLC

Comment: At time of inspection:
Pulling drill pipe. Prep to run casing.
Well Hole: 17,674'; Well Target TD: 17,674'. Surf csg set: 2,068'
Well is #7 of 8 to be drilled.
Drilling commence date: 04/16/2024.

Sound monitors installed outside at 4 corners of sound walls.
Gas monitors installed.
Enhanced sound barriers installed.
Low profile lighting installed for after dusk operations.
Site safety plan posted.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass					
Waddles	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 04/18/2024 at approximately 12:06 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: A07-04/Pad Location ID: 483509 Well Name(s): Braskaland A06-765. API: 123-44514. Location County: Weld County, Colorado Weather: Overcast, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Drilling DG. New well GPS coordinates: 40.505801 / -104.600489</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/21/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602579	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6517924