

WELL NAME: HILL RANCH 10-14V, API #: 071-07298, INSP. # 695109498



PHOTO 1: WELL SIGN





PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 4: Impacted soil identified at various locations through out location. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 5-22-24.





PHOTO 5: ANOTHER IMAGE OF IMPACTED SOIL. SEE PHOTO 4 FOR CORRECTIVE ACTION.





PHOTO 6: ANOTHER IMAGE OF IMPACTED SOIL. SEE PHOTO 4 FOR CORRECTIVE ACTION.





PHOTO 7: LEAK ON PUMPJACK GEAR BOX APPEARS TO BE THE SOURCE OF OILY WASTE IMPACTING SOILS AROUND PUMPMACK.
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. CA DATE 5-22-2024.



PHOTO 8: OILY WASTE INSIDE PRIME MOVER SECONDARY CONTAINMENT (ENGINE SKID). COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 4-23-2024.

