

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/22/2024

Document Number:

709100266

**FIELD INSPECTION FORM**

Loc ID 430695 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 ECMC Operator Number: 10773  
 Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC  
 Address: 5251 DTC PKWY STE 950  
 City: GREENWOOD State: CO Zip: 80111

**Findings:**  
10 Number of Comments  
5 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Krystal Heibel		krystal.heibel@state.co.us	
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent
Kyle Waggoner		kyle.waggoner@state.co.us	
Parrish, Melissa	970-397-3896	mparrish@fundareresources.com	
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430694	WELL	PR	03/17/2013	OW	123-36257	Razor 22-2712H	EI
435213	WELL	PR	09/01/2020	OW	123-38507	Razor 22D-2208B	EI
435214	WELL	PR	08/01/2022	OW	123-38508	Razor 22D-2703A	EI
435216	WELL	PR	08/01/2022	OW	123-38510	Razor 22D-2207A	EI

**General Comment:**

On April 11, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the Razor 22D pad location (Location ID: 430695). This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type			
Comment:	Entrance sign present		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Unused equipment located within bermed confinement of menthol tank.		
Corrective Action:	Comply with Rule 606		Date: <u>04/30/2024</u>
Type	WEEDS		
Comment:	Tumbleweeds observed around wellhead and around pumping unit.		
Corrective Action:	Comply with Rule 606		Date: <u>05/10/2024</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Other	Tank		
Comment:	Suspected spill of unknown volume located to the south east portion of the facility. See photo documentation for reference.		
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on a Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.		Date: <u>04/23/2024</u>
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Hydrocarbons observed leaking from the multiple well's stuffing boxes and along pumping unit's concrete slab. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>05/22/2024</u>
In Containment: No _____			
Comment: _____			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
			corrective date
Type: Other	# 1		
Comment:	Wildlife protections devices (netting) not adequate on the transfer pump. Hydrocarbons observed pooled above netting. See photo documentation.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: <u>05/02/2024</u>
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 430694 Type: WELL API Number: 123-36257 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435213 Type: WELL API Number: 123-38507 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435214 Type: WELL API Number: 123-38508 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435216 Type: WELL API Number: 123-38510 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100267	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519316">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519316</a>