

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/22/2024

Document Number:

709100268

FIELD INSPECTION FORM

Loc ID 430061 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD State: CO Zip: 80111

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Parrish, Melissa		mparrish@fundareresources.com	
Smith, Sydney		ssmith@fundareresources.com	Regulatory

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430062	WELL	PR	06/01/2023	OW	123-36029	Razor 14-1143H	EI

General Comment:

On April 11, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the Razor 14-1143H pad location (Location ID: 430061). This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Tumbleweeds observed within secondary containment.		
Corrective Action:	Comply with Rule 606	Date:	04/30/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (metal pipe, metal wheel, O-ring, pipe insulation, wood) located on site.		
Corrective Action:	Comply with Rule 606	Date:	04/30/2024
Type	OTHER		
Comment:	Hydrocarbons observed from exhaust around pumping unit. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	04/23/2024

Overall Good:

Spills:

Type	Area	Volume	
Other	Pump Jack		
Comment:	Hydrocarbons observed around a truck loadout. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	05/22/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Comment:	Wildlife protections devices (netting) not adequate on secondary containment. See photo documentation.		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	05/02/2024

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 430062 Type: WELL API Number: 123-36029 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100269	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519317