

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/22/2024

Document Number:

709100270

FIELD INSPECTION FORM

Loc ID 312142 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 8 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218843	WELL	PR	03/22/1993	OW	075-05606	VAN GUNDY, FRED 2	EI

General Comment:

On April 11, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the [VAN GUNDY, FRED68N54W/35NWNE](#) location (Location ID: 312142).
This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted on tanks		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/22/2024

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	Hydrocarbon drips and drabs observed throughout the location.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	04/23/2024
Type	TRASH		
Comment:	Trash (aluminum cans, rope, wood, pipe) observed within pit.		
Corrective Action:	Comply with Rule 606	Date:	04/29/2024

Overall Good:

Spills:

Type	Area	Volume	
Crude Oil			
Comment:	Hydrocarbon staining observed within the pit. Refer to photo documentation.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	05/22/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Other	# 1		corrective date
Comment:	Active pit on location is not registered with ECMC.		
Corrective Action:	Operator shall provide a Form 15: Pit Report/Permit, including the pit coordinates. Operator shall submit the Form 27 with accurate coordinates for the pit.	Date:	05/22/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Burrowing observed on secondary containment.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: <u>06/22/2024</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 218843 Type: WELL API Number: 075-05606 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100271	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519318