

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2024

Submitted Date:

04/22/2024

Document Number:

705000667**FIELD INSPECTION FORM**Loc ID 319384 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243368	WELL	SI	07/01/2021	GW	123-11159	COSLETT GAS UNIT E TRUE 1	PA
319384	LOCATION	AC			-	COSLETT GAS UNIT E TRUE-61N68W 1SWSE	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities									
Facility ID:	243368	Type:	WELL	API Number:	123-11159	Status:	SI	Insp. Status:	PA
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	319384	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403751086 received on 04/12/2024: On April 11, 2024, historically impacted soil was discovered below the former produced water vessel (PWV) location following decommissioning activities at the Cosslett GU E True 1 Production Facility site. Excavation and assessment activities are ongoing. The affected infrastructure has been removed and will not be replaced.	maclarej	04/22/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000668	PA well location; view SE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519411
705000669	Fenced excavations at facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519412