

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2024

Submitted Date:

04/22/2024

Document Number:

708302070

FIELD INSPECTION FORMLoc ID 335435 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262081	WELL	PR	10/19/2002	GW	045-07999	WILLIAMS GM 217-33	PR
262212	WELL	PR	10/19/2002	GW	045-08007	WILLIAMS GM 12-34	PR
262221	WELL	PR	10/19/2002	GW	045-08009	WILLIAMS GM 218-33	PR
298447	WELL	PR	05/31/2009	GW	045-17204	WILLIAMS GM 432-33	PR
298448	WELL	PR	09/22/2008	GW	045-17205	WILLIAMS GM 442-33	PR
298449	WELL	PR	09/22/2008	GW	045-17206	WILLIAMS GM 441-33	PR
298450	WELL	PR	09/22/2008	GW	045-17207	WILLIAMS GM 532-33	PR
298451	WELL	PR	09/22/2008	GW	045-17208	WILLIAMS GM 342-33	PR
298452	WELL	PR	09/22/2008	GW	045-17209	WILLIAMS GM 332-33	PR
298453	WELL	PR	06/03/2009	GW	045-17210	WILLIAMS GM 411-34	PR
298625	WELL	PR	09/26/2008	GW	045-17302	WILLIAMS GM 341-33	PR

General Comment:**COGCC Inspection Report Summary**

On 4/18/2024 at approximately 13:00, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/33NENE at Location ID #335435 in Garfield County, Colorado.

Normal production operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 11		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 11		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Inspected Facilities				
Facility ID:	262081	Type:	WELL	API Number: 045-07999 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	262212	Type:	WELL	API Number: 045-08007 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	262221	Type:	WELL	API Number: 045-08009 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298447	Type:	WELL	API Number: 045-17204 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298448	Type:	WELL	API Number: 045-17205 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298449	Type:	WELL	API Number: 045-17206 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298450	Type:	WELL	API Number: 045-17207 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	298451	Type:	WELL	API Number: 045-17208 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						
		Ditches				
		Gravel				
Gravel						
		Compaction				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302071	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520074