

Inspection Photos

Loc: 484357

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 4/22/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. Topsoil was not salvaged along the road and soils are very compacted.



Inspection Photos



Photo 2. Facing south toward the location.



Inspection Photos



Photo 3. Facing east toward along the access road near the location. There are area where soils are very compacted. Seeding was performed in this area however vegetation will not grow well in compacted soils.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484357 | Date: 4/22/2024

Inspection Photos



Photo 4. Facing east toward the flowline disturbance. The soils are not stabilized and are susceptible too erosion. There are displaced wattles shown at red arrows.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484357 | Date: 4/22/2024

Inspection Photos



Photo 5. Facing northwest at the location. These perimeter wattles are installed far away from the disturbance area and should be reinstalled for better erosion control.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484357 | Date: 4/22/2024

Inspection Photos



Photo 6. West side of the location. The are broken up straw wattles that need to be removed.



Inspection Photos



Photo 7. Facing west toward the flowline disturbance. The topsoil was not salvaged along the flowline and grey material was brought to the surface. It is likely soil amendments or topsoil will be needed for reclamation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484357 | Date: 4/22/2024

Inspection Photos



Photo 8. Facing east at the location. The stormwater wattles are displaced and have been run over by vehicles .

