

**KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628**



Debris and unused equipment




Debris. Unused equipment.

KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628



Debris from previous lack of weed maintenance.



Gas calibration out of compliance.

KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628



Debris



Debris

**KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628**




Debris



Replace labels when illegible

**KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628**



Stained soil covered with gravel



Oil leaks on engine

KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628



Debris



Debris

**KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628**



Location from Northeast corner



Location from Northwest corner

**KT Resources LLC
Ant Hill Unit 7-43
Location ID: 316628**



Location from Southwest corner



Location from Southeast corner