

Inspection Photos

April 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 320858

Inspection Document #: 714000704

Archuleta County, CO

Township: SWSE 17 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Carmelita Gallegos A 3
Location ID: 320858

4/23/24
+37.013091,-107.411452
236° SW



Photo 1. View of the disturbance taken from the access point facing center.



API #: 007-06325

Inspection Photos
Location Name: Carmelita Gallegos A 3
Location ID: 320858



Photo 2. View of rutting observed on either edge of the access point.
Additional stabilization is needed to minimize site degradation.

Inspection Photos
Location Name: Carmelita Gallegos A 3
Location ID: 320858

4/23/24
+37.012979,-107.411364
235° SW



Photo 3. View of cardboard and wood pallet debris observed along the southern edge of the disturbance.

Inspection Photos
Location Name: Carmelita Gallegos A 3
Location ID: 320858



Photo 4. View of surface material observed at the well head.

Inspection Photos
Location Name: Carmelita Gallegos A 3
Location ID: 320858



4/23/24
+37.013259,-107.411761
40° NE

Photo 5. View of the eastern interim reclamation area facing north east.
Vegetation comprised of smooth brome.

Inspection Photos
Location Name: Carmelita Gallegos A 3
Location ID: 320858



Photo 6. Reference area comprised of a grazed grass field/pasture.