

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4869 From entrance to location



Photo # 4870 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4871 Location



Photo # 4872 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4873 Location



Photo # 4874 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4875 Location



Photo # 4876 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4877 Barbed wire fence needs maintenance, barbed wire laying on ground/wildlife hazard



Photo # 4878 Barbed wire fence needs maintenance, barbed wire laying on ground/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4879 Barbed wire fence needs maintenance, barbed wire laying on ground/wildlife hazard



Photo # 4880 Barbed wire fence needs maintenance, barbed wire laying on ground/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4881 Barbed wire fence needs maintenance, barbed wire laying on ground/wildlife hazard



Photo # 4882 Barbed wire fence needs maintenance, barbed wire laying on ground/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4883 Mechanical condition - fluid leaking from tank valve



Photo # 4884 Mechanical condition - fluid leaking from tank valve

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad

Location #: 427395



Photo # 4885 Mechanical condition - fluid leaking from tank valve



Photo # 4886 Open ended load line