


Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Location is in close
proximity to Rule 411a Surface Water External Buffer.
Section/Township/Range: 21 7S95W**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



Photo # 4887 Culvert damaged/BMP needs maintenance



Photo # 4888 Culvert damaged/BMP needs maintenance

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



Photo # 4889 Culvert damaged/BMP needs maintenance



Photo # 4890 Culvert damaged/BMP needs maintenance & slope destabilized & sloughing

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



Photo # 4891 Culvert damaged/BMP needs maintenance & slope destabilized & sloughing



Photo # 4892 Culvert damaged/BMP needs maintenance & slope destabilized & sloughing

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



Photo # 4893 Culvert damaged/BMP needs maintenance & slope destabilized & sloughing



Photo # 4894 Culvert damaged/BMP needs maintenance & slope destabilized & sloughing

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



Photo # 4895 Slope destabilized & sloughing



Photo # 4896 Slope destabilized & sloughing

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



Photo # 4897 Culvert damaged/BMP needs maintenance & slope destabilized & sloughing



Photo # 4898 Culvert damaged/BMP needs maintenance & slope destabilized & sloughing

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 21-9C (PJ21) Pad
Location #: 427395



Photo # 4899 Exposed pipe in one of the areas where slope is destabilized & sloughing