

Inspection Photos

April 23rd, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 333346

Inspection Document #: 714000720

Archuleta County, CO

Township: NENW 8 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dungan 32-5 5-5
Location ID: 333346



4/23/24
+37.020554,-107.409000
139° SE



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Dungan 32-5 5-5
Location ID: 333346

4/23/24
+37.020554,-107.409000
98° E



Photo 2. View of the northern interim reclamation area facing east, vegetation comprised of smooth brome and rabbit brush.

Inspection Photos

Location Name: Dungan 32-5 5-5

Location ID: 333346



Photo 3. View of wattle BMPs that are no longer functioning and over filled with sediment.

Inspection Photos
Location Name: Dungan 32-5 5-5
Location ID: 333346



4/23/24
+37 036867,-107.419157
162° S

Photo 4. Inadequate/non functional storm water BMPs observed at location access point.

Inspection Photos
Location Name: Dungan 32-5 5-5
Location ID: 333346



Photo 5. Reference area comprised of indian rice grass and juniper.