

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2024

Submitted Date:

04/19/2024

Document Number:

708302054**FIELD INSPECTION FORM**

Loc ID 312634	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/> 2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 6 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE																
Operator Information: ECMC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1700 LINCOLN ST STE 3950</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>																			
Contact Information: <table border="1" style="width: 100%; border-collapse: collapse;"><thead><tr><th>Contact Name</th><th>Phone</th><th>Email</th><th>Comment</th></tr></thead><tbody><tr><td>, LARAMIE</td><td></td><td>cogccnotifications@laramie-energy.com</td><td></td></tr></tbody></table>				Contact Name	Phone	Email	Comment	, LARAMIE		cogccnotifications@laramie-energy.com									
Contact Name	Phone	Email	Comment																
, LARAMIE		cogccnotifications@laramie-energy.com																	
Inspected Facilities: <table border="1" style="width: 100%; border-collapse: collapse;"><thead><tr><th>Facility ID</th><th>Type</th><th>Status</th><th>Status Date</th><th>Well Class</th><th>API Num</th><th>Facility Name</th><th>Insp Status</th></tr></thead><tbody><tr><td>222064</td><td>WELL</td><td>PR</td><td>09/01/2017</td><td>GW</td><td>077-08666</td><td>OXBOW 18-1E</td><td>PR</td></tr></tbody></table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	222064	WELL	PR	09/01/2017	GW	077-08666	OXBOW 18-1E	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status												
222064	WELL	PR	09/01/2017	GW	077-08666	OXBOW 18-1E	PR												
General Comment: <p>COGCC Inspection Report Summary</p> <p>On 4/17/2024 at approximately 12:35, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, Oxbow/18-1E Pad at Location ID #312634 in Mesa County, Colorado.</p> <p>Normal production operations were observed.</p> <p>During the inspection, the following compliance issues were observed:</p> <p>1) Battery sign not visible/serviceable.</p> <p>A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.</p>																			

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign not visible/serviceable.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/19/2024

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	222064	Type:	WELL	API Number:	077-08666	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Check Dams				
		Gravel				
		Compaction				
Compaction						
		Culverts				
		Ditches				
Gravel						

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403762385	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6517168
708302055	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6517165