

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4826 From entrance to location



Photo # 4827 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4828 Location




Photo # 4829 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4830 Location




Photo # 4831 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4832 Location



Photo # 4833 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



**Photo # 4834 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**




Photo # 4835 Tank label contains inaccurate information

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4836 Debris



Photo # 4837 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4838 Debris



Photo # 4839 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4840 Tank containment damaged/buckling



Photo # 4841 Tank containment damaged/buckling

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad

Location ID: 427746



Photo # 4842 Tank containment damaged/buckling



Photo # 4843 Tank containment damaged/buckling