

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Ancillary equipment		# 1		
Comment:	electric			
Corrective Action:				Date:
Type: Bradenhead		# 1		
Comment:	PLumbed to surface			
Corrective Action:				Date:
Type: Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:				Date:
Type: Pump Jack		# 1		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241174 Type: WELL API Number: 123-08962 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/23/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>This inspection does not nullify any orders or corrective actions from the ECMC</u> <u>At time of inspection weather conditions were warm, calm, partly cloudy.</u>	medinaj	04/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505709	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6526099