

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2024

Submitted Date:

04/26/2024

Document Number:

699505748**FIELD INSPECTION FORM**Loc ID 328953 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248863	WELL	PA	03/12/2015	OW	123-16665	COUGHLIN RED VV 22-1	PA
439679	SPILL OR RELEASE	CL	10/30/2014		-	SPILL/RELEASE POINT	CL
447226	WELL	PR	05/01/2022	OW	123-43469	WAGNER 28N-E10HZ	PR
447227	WELL	PR	05/01/2022	OW	123-43470	WAGNER 27N-10HZ	PR
447228	WELL	PR	05/01/2022	OW	123-43471	WAGNER 2N-10HZ	PR
447229	WELL	PR	05/01/2022	OW	123-43472	WAGNER 28N-W10HZ	PR
447230	WELL	PR	05/01/2022	OW	123-43473	WAGNER 2C-10HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 6' chain link with barb wire

Corrective Action:

Date:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: Electric / automation

Corrective Action:

Date:

Type: Horizontal Heated Separator

9

Comment:

Corrective Action:

Date:

Type: Bird Protectors

10

Comment:

Corrective Action:

Date:

Type: LACT

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

9

Comment:

Corrective Action:

Date:

Type: Horizontal Separator

1

Comment:

Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 248863 Type: WELL API Number: 123-16665 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439679 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447226 Type: WELL API Number: 123-43469 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447227 Type: WELL API Number: 123-43470 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447228 Type: WELL API Number: 123-43471 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447229 Type: WELL API Number: 123-43472 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447230 Type: WELL API Number: 123-43473 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

At time of inspection location appears to be in compliance with ECMC rules.
At time of inspection weather conditions were clear, calm, warm.

User

medinaj

Date

04/26/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505749	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6526119