

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 10-30 Pad

Location # 335265



Apr 25, 2024 at 1:08:28 PM  
CO

Photo # 5104 From entrance to location



Apr 25, 2024 at 1:18:54 PM  
CO

Photo # 5105 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 10-30 Pad

Location # 335265



Photo # 5106 Location



Photo # 5107 Location





## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 10-30 Pad

Location # 335265



Apr 25, 2024 at 1:15:09 PM  
CO

Photo # 5108 Location




Apr 25, 2024 at 1:09:42 PM  
CO

Photo # 5109 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 10-30 Pad

Location # 335265



**Photo # 5110 PRV vent line cap damaged/PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 5111 PRV vent line cap damaged/PRV vent line does not comply with CECMC pressure safety device rules**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 10-30 Pad

Location # 335265



Photo # 5112 Debris



Photo # 5113 Debris