

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2024

Submitted Date:

04/29/2024

Document Number:

697602350

## FIELD INSPECTION FORM

Loc ID 332721 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250589	WELL	TA	02/25/2022	GW	123-18392	CORNELIUS 11-23	EI
250590	WELL	TA	02/25/2022	GW	123-18393	CORNELIUS 11-22	EI
485945	SPILL OR RELEASE	CL	01/24/2024		-	Cornelius 11-23	EI
485946	SPILL OR RELEASE	CL	01/26/2024		-	Cornelius 11-22	EI

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 485945. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
<b>Good Housekeeping:</b>				
Type	STORAGE OF SUPL			
Comment:	Pipeline is being stored on location			
Corrective Action:	Comply with housekeeping Rule 606.			Date: 05/06/2024
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date: _____
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities				
Facility ID: 250589	Type: WELL	API Number: 123-18392	Status: TA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 250590	Type: WELL	API Number: 123-18393	Status: TA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 485945	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 485946	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Environmental

Spill/Remediation:

Comment:

Remedial excavation has been backfilled. Remediation still open

Corrective Action:

Date:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602351	Photo 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527629">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527629</a>
697602352	Photo 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527630">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527630</a>
697602353	Photo 3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527631">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527631</a>