

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2024

Submitted Date:

04/29/2024

Document Number:

693807225**FIELD INSPECTION FORM**Loc ID 314617 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10779Name of Operator: SCOUT ENERGY MANAGEMENT LLCAddress: 13800 MONTFORT DRIVE SUITE 100City: DALLAS State: TX Zip: 75240**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist
Johnson, Mike	972-674-8679	Mike.Johnson@scoutep.com	Regional Manager
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229136	WELL	IJ	09/21/2020	ERIW	103-06219	U P 19-28	AC

**General Comment:**

Routine UIC inspection.

**Location****Lease Road:**

Type	Main		
comment:			
Corrective Action		Date:	
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	WAG skid		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 229136

Type: WELL

API Number: 103-06219

Status: IJ

Insp. Status: AC

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube:

Pressure or inches of Hg 2164

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: WEBR

TC:

Pressure or inches of Hg 0

Previous Test Pressure

Last MIT: 09/24/2020

Brhd:

Pressure or inches of Hg 0

Previous Test Pressure

AnnMTReq:

Comment:

Routine UIC inspection. Active injection at time of inspection.

Corrective Action:

Date:

Method of Injection: PUMP FEED

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Date Run: 4/29/2024 Doc [#693807225]

Page 4 of 5

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807226	Inspection photos 4/23/2024	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527626">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527626</a>