

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2024

Submitted Date:

04/29/2024

Document Number:

714200975

FIELD INSPECTION FORM

Loc ID: 430790 Inspector Name: Santistevan, Brittani On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430904	WELL	SI	06/01/2022	OW	123-36324	Campbell JF 17-41D	SI
433459	WELL	PA	09/02/2021	OW	123-37649	Campbell JF 17-6D-1	PA
460607	TANK BATTERY	AC	01/10/2019		-	Campbell JF PAD /17-41D battery	AC

General Comment:

THIS IS A FOLLOW UP INSPECTION.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	fencing, flowline remains at PA wellhead site. See attached photo.		
Corrective Action:	Comply with Rule 606/603.m.		Date: 01/17/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	panel		
Corrective Action:			Date:

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:	gas meter is not annually calibrated. See attached photo.	
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date: 05/29/2024
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 430904 Type: WELL API Number: 123-36324 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI; valves appear to be in a closed position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 06/14/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433459 Type: WELL API Number: 123-37649 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: PA; it appears flowline remains.

Corrective Action: Comply with Rule 606 Date: 01/17/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 460607 Type: TANK API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200193. All previous corrective actions assigned to this location have not been resolved. All previous corrective actions assigned to this location have been re-assigned with their original corrective action date. One new corrective action was observed at the time of re-inspection. Please review the narrative below for additional information.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground. On Monday, April 29, 2024 at approximately 1340, I, Inspector Brittani Santistevan, conducted an on-site inspection at CAMPBELL JF PAD 17-41D (PDC Energy), at location ID: 430790 in WELD COUNTY, Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. The flowline and fencing to a plugged and abandoned wellhead remains on location. Remove to comply with Rule 606/603.m. (Corrective action Date: January 17, 2024) See attached photo #3, 4. 2. It appears the gas meter has not been annually calibrated. Calibrate gas metering equipment annually to comply with rule 430.d.(1). (Corrective Action Date: May 29, 2024) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	04/29/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714200976	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528689