

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2024

Submitted Date:

04/29/2024

Document Number:

704900136

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 313360 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 10323 _____
 Name of Operator: ENTEK GRB LLC _____
 Address: 165 SOUTH UNION #366 _____
 City: LAKEWOOD State: CO Zip: 80228 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	
Wilson, Justin		jrwilson@blm.gov	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291259	WELL	SI	01/01/2014	GW	081-07395	BM FEDERAL 13-12 (OWP)	EI
485479	SPILL OR RELEASE	CL	02/22/2024		-	BM Federal #13-12 (OWP)	EI

General Comment:

On April 23-24, 2024 ECMC OWP Western EPS Jim Hughes conducted an environmental field inspection of the Entek BM Federal #13-12. For the most recent field inspection report of this facility, please refer to document #704900120.

Inspected Facilities

Facility ID: 291259 Type: WELL API Number: 081-07395 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485479 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>On April 23-24, 2024 ECMC OWP Western EPS Jim Hughes conducted an environmental field inspection of the Entek BM Federal #13-12. For the most recent field inspection report of this facility, please refer to document #704900120.</p> <p>Standing water on location is coming from a leaking 2" valve. A BLM tag is located on the 2" valve. The BLM personnel listed on the tag was notified on 4/24/24. Attempts to stop the release, at the request of the BLM, were unsuccessful. The 2" valve is broken.</p>	hughesjo	04/29/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
704900137	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528682