

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2024

Submitted Date:

04/29/2024

Document Number:

705000672

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 462548 \_\_\_\_\_ Maclaren, Joe \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**
 ECMC Operator Number: \_\_\_\_\_ 47120 \_\_\_\_\_  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP \_\_\_\_\_  
 Address: P O BOX 173779 \_\_\_\_\_  
 City: \_\_\_\_\_ DENVER \_\_\_\_\_ State: \_\_\_\_\_ CO \_\_\_\_\_ Zip: \_\_\_\_\_ 80217- \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 \_\_\_\_\_ Number of Comments

0 \_\_\_\_\_ Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249716	WELL	PA		GW	123-17519	MAYER 22-10L	PA
462548	Location	AC			-	FRED MAYER-63N67W-TANK 22SESE	EG

**General Comment:**

ECMC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 249716 Type: WELL API Number: 123-17519 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 462548 Type: Location API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000676	Fenced excavations and signage; Mayer facility	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528683">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528683</a>
705000677	OLF AIP; cut end sealed/ marked	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528684">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528684</a>